

# Technical Bulletin



April 13, 1965

TO ALL MAINTENANCE ENGINEERS - FOR IMMEDIATE ACTION

NO. MODELS

SUBJECT: VIBRATION IN GENERATOR COVER

18 M-162  
M-165

We have discovered the possibility of a vibration occurring at both ends of the generator cover - between the cover and metal mounting strip.

To eliminate this possibility, we are drilling a 5/32" hole, 1/2" from each end and securing same with rivets of appropriate size.

It is recommended this revision be applied to all existing instruments now in the field, or in transit.

DV/bf

Reprinted January 25, 1966 - 1-M

NOTE: This bulletin is a confidential letter to the Hammond dealer organization and is not for general distribution.  
HAMMOND ORGAN COMPANY, 4200 W. DIVERSEY AVE., CHICAGO, ILL., 60639