

# Technical Bulletin



HAMMOND ORGAN COMPANY  
DIVISION OF HAMMOND CORPORATION  
4200 DIVERSEY | CHICAGO, ILLINOIS 60639

TO ALL MAINTENANCE ENGINEERS - FOR IMMEDIATE ACTION

NO. MODELS  
R-100

SUBJECT: WIRING ERROR IN MUSIC LIGHT PLUG

In the music illumination power cable assembly, 011-044338, the black wires may terminate in pins 3 and 6 of P704. This is in error. The black wires should terminate in pins 1 and 4. See sketch below.

Be sure to inspect organs in your stock, and correct wire terminations if necessary.

The above applies to R-100 organs shipped before November 1, 1970.

P 704

