

# Technical Bulletin



HAMMOND ORGAN COMPANY  
DIVISION OF HAMMOND CORPORATION  
4200 DIVERSEY | CHICAGO, ILLINOIS 60639

TO ALL MAINTENANCE ENGINEERS - FOR IMMEDIATE ACTION

NO. MODELS

SUBJECT: PHILCO I.C.'s

N-Series


3/17/70

REFERENCE: Hammond Service News, Volume 1, No. 11.

In the referenced issue of the Hammond Service News, the difference between G. E. and Philco I.C.'s was explained.

Since that time a second version of the Philco I.C. has been used in production. These are gold color instead of black, and may be used interchangeably with the black ones.

For proper orientation a dot appears in one corner of the top of the I.C.'s. The dot identifies the location of pin 1 (ground), as shown in the illustration below. The gold I.C.'s are not notched. The dot is the only guide.



PHILCO

NOTE: This bulletin is a confidential letter to the Hammond dealer organization and is not for general distribution.