

HAMMOND ORGAN SERVICE LETTER

No. 100 Date Jan. 25, 1956

SUBJECT:

OILING OF GENERATORS

TO ALL SERVICE ENGINEERS:

VERY IMPORTANT

Some years back a Service Letter was sent to our dealer organization, advising them that the consoles as shipped from Chicago contained sufficient oil for the first months of operation. Until quite recently this procedure was followed, that is, sufficient oil being added at the factory before shipment so that it would not be necessary to oil the unit upon installation.

A recent analysis of this, has indicated to us that adding sufficient oil before shipment, at times would cause the oil to run into the vibrato scanner during shipment, and a certain amount of difficulty could ensue in vibrato operation.

With this in mind we would like to tell you that the instruments currently are being shipped without oil. We do, during the manufacture of the instrument, oil each individual bearing; however, you will notice that the oil cup on top of the running motor is dry. This also holds true for the reservoir on top of the generator which lubricates the various bearings.

It is therefore necessary, upon installing the console, that you instruct the owner how to oil the generator every four months, and at the same time demonstrate the oiling procedure, adding the actual oil.

NOTE: This bulletin is a confidential letter to the Hammond dealer organization and is not for general distribution.