

# Technical Bulletin

HAMMOND ORGAN

"music's most glorious voice"

April 12, 1966

NO. MODELS

TO ALL MAINTENANCE ENGINEERS - CHANGES

SUBJECT: Transistor and diode commercial part  
Replacement recommendations

33 H-100 Series

ASSEMBLY	SYMBOL	HAMMOND PART NO	COMMERCIAL
Power Supply AO-71-1	Q702	01-1205-OP	2N1541
	Q701	01-1201-0	2N1303
	D704	01-2303-3	IN1766
	D701, D702, D703	01-2405-1	IN2069
	D707		
	D705, D706	01-2601-0	IN3604
Percussion & Reiteration Driver Assembly AO-30223-0	Q201, Q202	01-2101-0	2N2712
	D202	01-2303-3	IN1766
	D201	01-2601-0	IN3604
Harp Sustain Keyer Assembly AO-30270-0	All Transistors	01-2101-0	2N3393
Brush & Cymbal Assembly AO-30275-0	Q904	01-2106	2N3394
	Q901, Q903	01-2104	2N3393
	Q902, Q906	01-2108	2N3391
Percussion Amplifier Assembly AO-72-1	D101	01-2601-0	IN3604
Celeste Drive Amplifier AO-30268-2	Q810	01-2110	2N3416
Chorus Drive Amplifier AO-30268-1	Q810	01-2110	2N3416
Non-Vibrato Drive Amplifier AO-30266-0	Q801, Q802	01-2110	2N3416

NOTE: This bulletin is a confidential letter to the Hammond dealer organization and is not for general distribution.  
HAMMOND ORGAN COMPANY, 4200 W. DIVERSEY AVE., CHICAGO, ILL., 60639

Technical Bulletin #33 sheet 2 of 2

<u>ASSEMBLY</u>	<u>SYMBOL</u>	<u>HAMMOND PART NO</u>	<u>COMMERCIAL EQUIVALENT</u>
Vibrato Drive Amplifier AO-30266-0	Q804, Q805	01-2104	2N3393
	Q806	01-2114	(Mot. 2N3501 (RCA 2N3440 (G.E. 2N3589
Scanner Preamps (4) AO-30267-0	Q807	01-2109	2N3393
	Q808	01-2104	2N3393
	Q809	01-2110	2N3416