

Technical Bulletin



HAMMOND ORGAN COMPANY
DIVISION OF HAMMOND CORPORATION
4200 DIVERSEY | CHICAGO, ILLINOIS 60639

January, 1968

TO ALL MAINTENANCE ENGINEERS - CHANGES

NO. MODELS

SUBJECT: REVISED E-100, E-200, E-300 SERVICE MANUAL

56 E-100
E-200
E-300

Attached is a revised copy of the E-100 - E-200 - E-300 series Service Manual.

We suggest you discard your earlier copies.

While a portion of this later manual is similar to the previous issue, we particularly call your attention to the adjustment procedure on Pages 31, 32, and 33. These adjustments should be checked before the instrument is demonstrated on the sales floor, or upon delivery to the user.

Reprints of technical bulletins with reference to these instruments will be found on Pages 37, 38, 39, and 40.

Please review the entire manual carefully so as to make yourself more familiar with these products, and your adjustment and repair work will be easier to accomplish

CJS/rf
Attachment

NOTE: This bulletin is a confidential letter to the Hammond dealer organization and is not for general distribution.