

Hammond Service News

Volume 2 Number 4

Model N - Series

SUBJECT: CHANGES IN PARTS CHARACTERISTICS

REFERENCE: N SERVICE MANUAL HO-436, NOVEMBER, 1969

In Figure 5-14, Voicing Board No. 3, the following resistors should be $\pm 5\%$:
R1, R2, R9, R12, R13, R24, R25.

In Figure 5-13, Voicing Board No. 2, R1 is now 180 K $\pm 5\%$; R2 is now 330 K $\pm 5\%$.
The following resistors are now $\pm 5\%$: R4, R6, R19. R16 is now 1K; R32 is now
47K. The purpose of these changes is to improve Dynamute signal output. It
is recommended that these changes be made in the field whenever complaints
are received concerning insufficient Dynamute volume.

The changes described above are incorporated in current production.