

# Hammond Service News

Volume 2

Number 2

Model H-100/262,  
X-77/GT

**SUBJECT:** POWER SUPPLY

**REFERENCES:** H-100 Service Manual, HO-426, February 1970,  
Figure 52  
X-77 Service Manual, HO-703, December 1969,  
Figure 41

In order to accommodate a change in the windings of pedal latching solenoids in recent production, the values of R722 and R723 have been interchanged. R722 is now 22 ohms; R723 is now 18 ohms. Wattage remains unchanged.