

Technical Bulletin



June 10, 1966

TO ALL MAINTENANCE ENGINEERS - CHANGES

NO. MODELS

SUBJECT: SCANNER-RUN MOTOR ASSEMBLIES

37 A11

Our Service Department supply of Run Motor and Scanner Assemblies for all model instruments has become critically short.

We have always endeavored, with some degree of success, to comply with your requests for shipment as soon as orders are received. This is becoming increasingly difficult due to the slowness of return of units from dealers.

There is a definite monetary value in your favor invested in the original Run Motor and Scanner Assemblies and we urge you to send all such units in your possession back to the factory for credit, less repair charges.

This will work out to your financial advantage and enable the Hammond Organ Company to create a shelf stock so that we may serve you more expeditiously.

DV/bf

NOTE: This bulletin is a confidential letter to the Hammond dealer organization and is not for general distribution.
HAMMOND ORGAN COMPANY, 4200 W. DIVERSEY AVE., CHICAGO, ILL., 60639